THE POWDER HOUSE SCHOOL RETRO-FIT - SD ESTIMATE

Estimated rates 2Q 05 Gross Floor Area 100,653 SF

Gross	Floor Area 100,653 SF CSI Div.	As Drawn COST \$	Cost savingsCOST \$
02	SITE CONSTRUCTION	1,128,724.	1,068,596.
03	CONCRETE	25,525.	12,763.
04	MASONRY	125,272.	16,865.
05	METALS	128,119.	105,984.
06	WOOD & PLASTICS	223,803.	209,503.
07	THERMAL & MOISTURE PROTECTION	19,838.	9,919.
08	DOORS & WINDOWS	1,025,985.	590,035.
09	FINISHES	1,262,568.	1,262,568.
10	SPECIALTIES	155,902.	133,401.
11	EQUIPMENT		
12	FURNISHINGS	23,891.	23,891.
13	SPECIAL CONSTRUCTION		
14	CONVEYING SYSTEMS	115,000.	90,000.
15	MECHANICAL	1,888,631.	1,888,631.
16	ELECTRICAL Sub-total \$	1,687,000. 7,810,257.	1,687,000. 7,099,157.
	RTU replacement for As Drawn and Repair for Cost savings Sub-total \$	400,000 8,210,257	23,000 7,122,157
	General Conditions Bond & Insurance Overhead and Profit Estimating Contingency	697,872. 133,622. 406,879. 944,863.	605,383. 115,913. 352,955. 819,641.
	CONSTRUCTION Total \$ (at 2Q 05)	\$10,393,492	\$9,016,049
	Hazardous Material Abatement Seismic mitigation Sub-total \$	190,000 1,650,000 12,233,492	190,000 1,650,000 10,856,049
	Workstations Stage Equipment Room Signage Traffic Signal Premium for moving and leasing space for PIC during construction* Allowance for roof penetrations	130,000 25,000 25,000 100,000 200,000 75,000	25,000 100,000 200,000 75,000
	GRAND TOTAL \$	12,788,492	11,386,049
	Escalation for 1.5 years = 15% ESCALATION (Mid-Construction 12/06 = 15%)	1,918,274 \$14,706,766	1,707,907 \$13,093,957

^{*} Premium for PIC to remain in building =\$400,000

EBBOS05012-102 Printed 9/19/05 9:28 AM Rider Hunt Levett Bailey Construction Consultants

THE POWDER HOUSE SCHOOL RETRO-FIT - SD ESTIMATE

What the "Cost Savings" project would be like:

- No new window openings
- No new elevator, just a new lift at the existing front entrance. This entrance would need to be modified to be accessible.
- The existing elevator would still need to be removed / replaced because it does not meet dimensional requirements.
- No interior glazing at doors and no glazed sidelights by the doors.
- Minimal parking area changes and fewer parking spaces.
- No exterior masonry cleaning and re-caulking.
- Roof top HVAC units would be repaired, not replaced.
- No stage equipment